




Rexarc

INTERNATIONAL, INC.

FIXED FLOW FITTING




Installation
is **FAST**
EASY



Delivers the proper gas flow to the right place **ALL THE TIME.**

- Tamper-proof design – flow rate cannot be altered at point of use
- Can be installed on the “GAS IN” connection behind your welding machine or wire feeder
- No moving parts, no maintenance, cannot break
- Flow rate is “factory set” to your specific gas requirements.
- Eliminates gas surges, IMMEDIATE ROI



Installation on wire feeder

**REXARC – SAVING YOU TIME
AND MONEY WITH INNOVATION**

P.O. Box 7, West Alexandria, Ohio 45381 USA
Telephone 937-839-4604
Fax 937-839-5897

www.rexarc.com
info@rexarc.com

Call or email to find out more!